

Mi-17-1V helicopter and its modifications



Service bulletins and other design documentation for the Mi-17-1V helicopter and its modifications

SERVICE BULLETINS:

Prima-KV HF radio (Replacement of the Yadro-1 HF radio)

T3272-BU-AB, T3273-BE-AB

Almaz-UPM audio warning system (Replacement of the RI-65B voice informer)

T3036-BE-G, T3035-BU-AB, T3036-BE-AB, T3310-BU/BE-AB

Prima-MV VHF radio (Replacement of the Baklan-20 (Orlan-85) guard VHF radio)

T3525-BE-G

Other design documentation:

Prima-DMV-1 V/UHF radio (Replacement of the Baklan-20 (Orlan-85) VHF radio)

RPA-500 SAR airborne direction finde (installation)

SSKM-R satellite aircraft tracking system terminal (installation)